


Thermister (soil Temp)

	Wire	Instrument
red/copper - 3 H	white	white
green/ss - Ex 1	black	shield.

ML 2x (Soil Moisture)

red - Ex 3	red	power +
blue - Ex <u>gnd</u>	blue	power 0
yellow - 5 H	org.	Out Hi sig
green - 5 <u>gnd</u>	green	Out Lo sig
Copper - 5 <u>gnd.</u>	Shield	screen

Back - case



Back ^{Connect} Instruments

